

IMPORTANT SAFETY WARNING

Rewaco Trikes - RF1 GT/LT/ST



We have become aware that some RF1 Models, sold between February 2005 and July 2012 may have a manufacturing defect.

This defect may cause a weld joint to break and may lead to loss of steering.

If you own a RF1 model please check the serial number as shown in the diagram below

W09RF1....LR38...

The affected models have serial numbers W09RF1A2F5LR38075 to W09RF1C2FCLR38371 and were sold in the UK

If you have an affected RF1 model **please stop using it immediately** and return it to the retailer it was purchased from for an inspection and fitting of a reinforcement bracket.

If you have any queries please do not hesitate to contact us on Tel: 01279 -730695 on Mon - Fri 9 am – 5 pm

We wish to thank you for your co-operation and apologise for any inconvenience.

Rewaco Trikes UK Ltd 47 Sheering Rd Harlow Essex CM17 0JN.

Tel/Fax: 01279 730695

Email: info@RewacoTrikesUK.co.uk

www.RewacoTrikesUK.co.uk